



Coping stones dismantled prior to reinstatement



North west copings dismantled



Raking out—west gable—prior to repointing



South west copings dismantled

EUXTON PARISH CHURCH—REPAIRS

Progress Photographs dated 9th December 2021

58040/N



Position of last rafter

Construction of new secret gutter—at west end of south nave



Secret gutter set out in relation to last rafter position
(to gain maximum depth / upstand against copings)



Rafter below

EUXTON PARISH CHURCH—REPAIRS

Progress Photographs dated 9th December 2021

58040/O